Tool holders and adapters

For BDS core drills with Weldon shanks - suitable for adaptation to external systems.

Tool holders for BDS core drills with Weldon arbor. Three systems are available; they allow for a friction-locked, comfortable and secure connection between the core drill and the magnetic core drilling machine.

Tool holder for BDS core drills with Weldon shanks 19 mm $(\frac{3}{4})$ ")

Tool holder for BDS core drills with Weldon shanks 19 mm ($^{3}/_{4}$ ") and 32 mm ($^{1}/_{4}$ ")

Tool holder for BDS core drills with 19 mm Weldon shanks (3/4") and 32 mm $(1^1/4")$



KEYLESS QUICK-CHANGE DRILL CHUCK SYSTEM

ORDER NO.		SPINDLE HOLDER		
	ZSS 200	MK 2		
	ZSS 300	MK 3		
	With autom	ith automatic internal lubrication for co		

with Weldon shank 19 mm (³/₄"). With hose and quick acting coupling. Quick tool change without any chuck key.



INDUSTRIAL ARBOR WITH MANUAL INTERNAL LUBRICATION

ORDER NO. SPINDLE HOLDER

ZIA 219-M	MK 2
ZIA 319-M	MK 3
ZIA 419-M	MK 4
For core drills	s with 19 mm Weldon shank (3/4")
ZIA 332-M	MK 3
ZIA 432-M	MK 4
For core drills	s with 32 mm Weldon shank $(1^1/4'')$



INDUSTRIAL ARBOR WITH AUTOMATIC INTERNAL LUBRICATION

ORDER NO.	SPINDLE HOLDER			
ZIA 219-KN	MK 2			
ZIA 319-KN	MK 3			
ZIA 419-KN	MK 4			
For core drills with 19 mm Weldon shank (3/4")				
ZIA 332-KN	MK 3			
ZIA 432-KN	MK 4			
For core drills with 32 mm Weldon shank ($1^1/4''$)				
With hose and quick acting coupling.				



REDUCING BUSH DIN 2185

ORDER NO	. OUTSIDE	INSIDE	
ZRH 210	MK 2	MK 1	



EXTENSION BUSH DIN 2178 ORDER NO. OUTSIDE INSIDE ZVH 220 MK 2 MK 2 ZVH 230 MK 2 MK 3

MK 3

MK 3

MK 2

MK 3

ZVH 320

ZVH 330

Adapters for BDS core drills. With the appropriate adapter, BDS core drills with Weldon shanks are compatible with standard machines or tool holder systems on the market.

